



CAUTION



Before proceeding with repair work, all sources of power to the machine must be secure with a locking device and tagged out.