WARNING

STORED ENERGY HAZARD!
Dissipate rotation and Lockout/Tagout before servicing.

Made 11.09.26 - www.DEenergize.com - ID: WAA087DE