



# **DANGER**

**Before proceeding with repair work, all sources of power to the machine must be secure with a locking device and tagged out.**