WARNING

BEFORE CLEANING, OILING OR REPAIR, ALL SOURCES OF POWER TO THE MACHINE MUST BE SECURE WITH A LOCKING DEVICE AND TAGGED OUT